

FOOD MACHINE INSTRUCTIONS

ADULTS MUST SUPERVISE THESE MACHINES AS THEY CAN BE VERY DANGEROUS!

Yield Information

Cotton Candy One 5lb bag of sugar makes approximately 90 servings

SnoKone ICE: One 8 lb bag of ice makes 21 servings. SYRUP: mix one 5 lb. bag of sugar and 1 can of cherry mix. Makes 125 servings.

Popcorn One 4 lb bag of popcorn seeds makes approx. 36 servings. One gallon of corn oil is sufficient to pop around 28 lbs. of popcorn. One container of salt makes a lot of popcorn.

Slush Machine 3 gallons of bottled soda (off brand cola or punch works well). The machine cannot be in the sun or it will not freeze up.

Cotton Candy Machine

Warning---Failure to follow these instructions will damage the machine.
The minimum repair bill for repairing the machine is \$95.00

- 1) Never put water or any liquid into the machine.
- 2) Never put any mixes or colors into the machine
- 3) Only use 100% sugar
- 4) Do not overfill spinner head
- 5) After use clean bowl with warm water in a Pareve sink. **DO NOT GET THE MACHINE ITSELF WET.**
- 6) Fill center spinner head with plain sugar
- 7) Turn on both switches and twirl away

Popcorn Machine

IMPORTANT: Make sure kettle head gear is engaged with spinning gear on the roof of the machine (failure to do this will result in the popcorn jamming up the kettle).

1. Turn on all switches on machine and pour 2 oz. of oil into kettle.
2. Wait 4-5 minutes until oil is hot (you can see if the oil is hot enough by dropping a kernel into the kettle and seeing if it bubbles).

3. Pour 12 oz. of popcorn kernels into kettle
4. Pour some salt (about one tablespoon) into kettle.
5. When the popping stops dump out popcorn and begin again (after the first batch, only wait one minute between oil and seeds).

Snokone Machine

-----DANGER----- NEVER PUT HANDS INTO ICE GRINDER

- 1) Turn on ice grinder.
- 2) Pour ice into grinder.
- 3) Use handle to grind ice. (Don't press too hard so that machine won't jam)
- 4) Scoop into cups.
- 5) If machine jams up turn off and let the ice melt.
- 6) When not grinding ice turn off machine.

Snokone Mix

- 1) Fill a separate container 2/3 full with cold water
- 2) Pour sugar into water until sugar stops dissolving and remains on bottom
- 3) Add dry cherry drink mix until solution turns a nice shade of red.
- 4) Put a scoop of ice into cup.
- 5) Pour syrup over ice until the ice is red (be generous, it tastes better!)

Super Popper Commercial Popcorn Machine

1. Plug in machine & light pilot
2. Pour in 15 oz oil, wait 3 min.
3. Pour in 30 oz. of seeds and half a shot glass of salt
4. When popping is done lift large handle and dump out popcorn, turn flame to pilot setting when finished popping.
5. Once hot you don't have to wait between batches